



Aerospace requirements

The following are guide-lines for potential suppliers wishing to contribute to any aerospace contracts awarded to Tru-Form.

1. Aerospace Requirements

(a) Right Of Access

Supplier will grant the Company, Companies Customer, or Regulatory Authority access to their QMS, Records, Process Facilities and supply chain.

(b) Records

Supplier must retain the manufacturing records for a minimum of 5 years or as defined in the contract.

(c) Flow-down

Supplier must inform (flow-down) their supply chain of the applicable requirements as stated here in.

(d) Traceability

Supplier shall ensure that all product to be identified by Lot / Batch code, visible on delivery note and or product label, this information should be traceable to product manufacture.

(e) Non-Conforming Product

Supplier will notify Company of any supplied product known to be non-conforming by the supplier.